

SIENA D-4

Ⓓ **Montageanleitung**

Ⓐ **Handleiding voor de montage**

Ⓓ **Montaj talimatı**

Ⓕ **Notice de montage**

Ⓒ **Montážní návod**

Ⓗ **Szerelési útmutató**

Ⓖ **Assembly Instructions**







Ⓐ **Instrukcja montażu**

Ⓔ **Инструкция по монтажу**

Ⓘ **Istruzioni di montaggio**





Ⓐ **Návod na montáž**



Ⓓ **Instrucțiunile de montaj**



**Uwaga – Upozornini – Achtung – Attention – Caution – Figyelem
Attenzione – Opgelet – Вниманіе – Atentie – Upozornenie – Dikkat**

PL	Czyszczenie należy wykonać wyłącznie za pomocą ściereczki lub lekko nawilżonego ręcznika. Nie stosować środków czyszczących do szorowania.
CZ	Čistění je nutné vykonávat výhradně pomoci utěrky nebo lehce navlhčeného ručníku. Nepoužívejte čisticí prostředky obsahující abrazivní částice.
D	Bitte nur mit einem Staubtuch oder leicht feuchtem Lappen reinigen. Keine scheuernden Putzmittel verwenden.
GB	Please only clean with duster or damp cloth. Do not use any abrasive cleaners.
F	Le nettoyage se fait uniquement à l'aide d'un torchon ou d'une serviette légèrement mouillée.
HU	A tisztítás kizárólag törölrüha vagy enyhén nedvesített törölköző segítségével végezhető. Súroló hatású tisztítószerket nem szabad használni.
I	Pulire esclusivamente con un panno o un asciugamano umido.
NL	Reinig allen met een stofdoek of een lichtjes vochtige doek. Gebruik geen schurende poetsmiddelen.
RU	Очищайте от пыли тряпкой или слегка влажной ветошью. Не допускаются применение чистящих средств, не предназначенных для ухода за мебелью.
RO	Curabare trebuie efectuată numai cu o cârpă sau cu un prosop ușor umed. Nu utilizați agenți de curabare abrazivi.
SK	Čistení je nutné vykonávať výhradne pomoci utierky alebo ľahko zvlhnutým ručníkom. Nepoužívajte čistiace prostriedky obsahujúci abrazívne častice.
TR	Lütfen sadece bir toz bezile veya hafif nemli yumusak bir bezle siliniz. Asindirici temizlik malzemeleri kullanmayiniz.






WYMIARY ELEMENTÓW
PART GUIDE
MASSE DER BAUTEILE

No.	L[mm]	W[mm]	T[mm]	Stc.	Colli
1	575	1960	16	1	2/3
2	571	1928	16	1	2/3
3	1980	575	16	1	1/3
4	1980	575	16	1	1/3
5	1894	571	16	1	1/3
6	1894	571	16	1	1/3
7	945	571	16	1	2/3
8	552	475	16	2	2/3
9	552	475	16	6	2/3
10	1928	70	16	2	2/3

No.	L[mm]	W[mm]	T[mm]	Stc.	Colli
11	1920	480	3	2	1/3
12	1920	492	3	2	1/3
13	199	940	16	3	3/3
14	120	450	16	3	3/3
15	120	450	16	3	3/3
16	100	888	16	3	3/3
17	458	904	3	3	3/3
18	1888	469	16	1	3/3
19	1260	469	16	1	3/3
20	1260	469	16	1	3/3
21	1888	469	16	1	3/3



N15
M4x25 x...(10)

E19
x...(10)

I9
x...(34)

I12
x...(6)

W4
x...(130)

K5
x...(6)

G29
6x11 x...(12)

S1
x...(1)

S17
x...(24)

K1
ø15x12 x...(6)

F2
x...(26)

S5
x...(1)

W2
x...(1)

C4
Z350D x...(12)

D4
PZ350D x...(12)

G6
3x13 x...(16)

P4
x...(8)




H7
x...(3)

S4
x...(2)






A1
ø7x50 x...(34)

G4
4x16 x...(24)

B1
ø8x35 x...(78)






I












P4		x...(4)
B1		x...(36)

II





P4		x...(4)	D4		x...(12)	B1		ø8x35	x...(18)	S4		x...(2)	H7		x...(3)
----	---	---------	----	---	----------	----	---	-------	----------	----	---	---------	----	---	---------

III x3



G6		W2	
3x13	x...(12)		x...(1)
A1		K1	
Ø7x50	x...(6)	Ø15x12	x...(6)
B1		K5	
Ø8x35	x...(24)		x...(6)

IV



V

Diagram illustrating the assembly of the back of the device, showing the installation of panels 5, 6, and 7.

Panel 5 is shown being attached to the main unit using screws labeled A1.

Panel 6 is shown being attached to the main unit using screws labeled A1.

Panel 7 is shown being attached to the main unit using screws labeled A1.

A detail inset shows the installation of a Z-profile (W2) into the back of the device.

Parts List:

Part	Quantity
W2 (L-shaped bracket)	x... (1)
A1 (Screw, ø7x50)	x... (4)

VI



Diagram illustrating the assembly of the backrest panel (6) and the attachment of the backrest frame (2) to the main frame (5) using screws (A1) and brackets (W2).

The diagram shows the backrest panel (6) being attached to the main frame (5) using screws (A1). The backrest frame (2) is also shown being attached to the main frame (5) using brackets (W2).


Warning: The backrest panel (6) must be attached to the main frame (5) using the correct orientation (smiley face) and not the incorrect orientation (sad face).

Legend:





- W2: Bracket (x... (1))
- A1: Screw (x... (4))




W2  x...(1)	A1  ø7x50 x...(12)
--	--




VIII






1










W2	A1
	
x...(1)	x...(8)

IX






S17		S1		W4	
	x...(24)		x...(1)		x...(106)




$$a=b$$






X






G4		C4		E19		N15	
4x16	x...(24)	Z350D	x...(12)	x...(4)		M4x25	x...(4)

XI



F2  x...(26)	S5  x...(1)
---	---



E19	N15
 x...(6)	M4x25 x...(6)

XIII

